



- (ii) The no load current of a transformer is 15A at a p.f. of 0.2, when connected to a 460V, 50Hz supply. If the primary winding has 550 turns, calculate (6)
- the magnetizing component of no load current
  - the iron loss
  - the maximum value of the flux in the core.

**(OR)**

- b) (i) A 500/250 V, 50Hz, single phase transformer have the following readings,
- O.C. Test:** 500 V, 1 A, 50 W (L.V. side open),  
**S.C. Test:** 25 V, 10 A, 60 W (L.V. side shorted)

Determine: (i) The efficiency on full load, 0.8 lagging p.f. (ii) The voltage regulation on full load, 0.8 leading p.f. (iii) The efficiency on 60% of full load, 0.8 leading p.f. (iv) Draw the equivalent circuit referred to primary & insert all the values in it.

23. a) Explain any two different methods of speed control of three-phase induction motor.

**(OR)**

- b) (i) Discuss in detail about the principle of operation of three phase induction motor. (8)  
(ii) Write short notes about single phase capacitor start induction motor. (6)

24. a) (i) Describe any one method to determine voltage regulation of synchronous generator. (8)  
(ii) A 3 phase 12 pole star connected alternator has 72 slots and 6 conductors per slot. If it is driven at 500 rpm, calculate the induced emf (line to line). Assume coil span as 150 electrical and flux per pole 40 mWb. (6)

**(OR)**

- b) (i) Explain the operation of variable Reluctance stepper motor with neat diagram. (8)  
(ii) Describe the construction and operation of hysteresis motor. (6)

25. a) (i) Explain the structure of electrical power system with single line diagram. (8)  
(ii) With a neat diagram, explain the operation of EHVDC transmission system. (6)

**(OR)**

- b) (i) Explain the following types of insulators with neat diagrams. (8)  
a) Pin-type insulators b) Suspension type insulators.
- (ii) Write short notes on construction of cables with neat diagram. (6)

\*\*\*\*\*